

**Inspection Photos**  
**Location Name: Laramie Well 045-13703**  
**3/6/2018**



**NE corner of SPCC looking N**



**Unstable rock slope above tank battery looking NE**



**Impact damage to decommissioned AST**



**Location looking North**