

Inspection Photos  
Location Name: Cody 2  
API: 05-057-05136



**Photo 1. Overview of location taken at entrance facing northeast.**

Inspection Photos  
Location Name: Cody 2  
API: 05-057-05136



**Photo 2. Stained soil and free fluid south of wellhead.**



**Photo 3. Stained soil and free fluid south of wellhead.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 689800875

Inspection Photos  
Location Name: Cody 2  
API: 05-057-05136



**Photo 4. Stained soil and free fluid south of wellhead.**



**Photo 5. Stained soil and free fluid south of wellhead.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 689800875