

Inspection Photos
Location Name: DF Ranch #1161-17-42
Facility ID # 415195



Photo 1. wellhead looking south



Photo 2. location looking southwest

Inspection Photos
Location Name: DF Ranch #1161-17-42
Facility ID # 415195



Photo 3. stained soil at wellhead



Photo 4. stained soil at base of pumpjack

Inspection Photos
Location Name: DF Ranch #1161-17-42
Facility ID # 415195



Photo 5. whole in fence around pumpjack



Photo 6. stained soil at base of engine

Inspection Photos
Location Name: DF Ranch #1161-17-42
Facility ID # 415195



Photo 7. stained soil near load out



Photo 8. trash in treater house

Inspection Photos
Location Name: DF Ranch #1161-17-42
Facility ID # 415195



Photo 9. trash in treater house




Photo 10. stained soil in treater house

Inspection Photos
Location Name: DF Ranch #1161-17-42
Facility ID # 415195



Photo 11. incorrect well names