

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 1. Signs at wellhead



Photo 2. stained soil in engine house

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 1. Stained soil under pumpjack



Photo 2. stained soil around wellhead