

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 1. Signs at wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 3. stained soil at wellhead



Photo 4. stained soil in engine room

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 5. stained soil south from wellhead



Photo 6. black fluid in bucket

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 7. stained soil at base of pumpjack



Photo 8. stained soil under pumpjack weights

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 9. stained soil west side up motor room



Photo 10. stained soil in engine house

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 11. stained soil at load out



Photo 12. unmarked riser

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 13. unmarked risers



Photo 14. stained soil in treater house

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 15. trash in treater house



Photo 16. stained soil in treater house

Inspection Photos
Location Name: DF Ranch 1161-17-12
Facility ID # 415442



Photo 17. BBL CAP. Not marked