



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Feb 27, 2018 11:10:55 AM MST
Server Receive Date:	Feb 27, 2018 11:11:05 AM MST
Reference Number:	20180227-1873948709
Location:	Aztec, NM 87410, United States
	Feb 27, 2018 11:10:40 AM MST [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	Feb 5, 2018
Well Name	ROBERTSON GAS UNIT 19-01 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Other Clean up Operator Debris Clean Up Land Owner Debris Replaced/Repaired Tank Signs

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



