



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Mar 5, 2018 1:36:08 PM MST
Server Receive Date:	Mar 5, 2018 1:36:22 PM MST
Reference Number:	20180305-1874293125
Location:	3989 Co Rd 510, Ignacio, CO 81137, USA Mar 5, 2018 1:35:59 PM MST [View Map]

Information

Name	reclamationtablet
Date	Mar 5, 2018
Well Name	MAYFIELD GAS UNIT A 1
API Number	50670655900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Seeding

Picture North to South



Picture East to West



Picture West to East



Additional photos



Additional photos

