



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Clay Elkins (celkins@gobrainstorm.net)
Submission Date: Mar 6, 2018 7:40:11 AM MST
Server Receive Date: Mar 6, 2018 9:12:04 AM MST
Reference Number: 20180306-1874328014
Location: 3601 N 1st St, Bloomfield, NM 87413, United States
Mar 6, 2018 7:39:51 AM MST [[View Map](#)]

Information

Name: celkins@gobrainstorm.net
Date: Mar 5, 2018
Well Name: CRAIG, HELEN GAS UNIT 2
Select State: Colorado
Work type: COGCC Inspection AR
Action Complete: Compliance Inspection Actions
Erosion Repairs
Clean Up Land Owner Debris
Clean Up Contaminated Soils

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

