

Inspection Photos

Location Name: **FEDERAL 1-30**

API – 05-103-08096



Battery sign –missing nearest public access road & emergency contact

Well

Inspection Photos

Location Name: **FEDERAL 1-30**

API – 05-103-08096



Weeds/Brush around equipment



Weeds/Brush around equipment



Inspection Photos

Location Name: **FEDERAL 1-30**

API – 05-103-08096



Weeds/Brush around equipment



Crude oil tank label

Inspection Photos

Location Name: **FEDERAL 1-30**

API – 05-103-08096



Production water tank label



Bird protector –not able to determine if present.

Inspection Photos

Location Name:

FEDERAL 1-30

API – 05-103-08096



Weeds/Brush/Erosion cuts in blow down pit



Weeds/Brush/Erosion cuts in blow down pit

Inspection Photos

Location Name: **FEDERAL 1-30**

API – 05-103-08096



Weeds/Brush in blow down pit



Weeds/Brush in blow down pit



Inspection Photos

Location Name: **FEDERAL 1-30**

API – 05-103-08096



Weeds/Brush/Erosion cuts in blow down pit



Weeds/Brush/Erosion cuts in blow down pit

Inspection Photos

Location Name: **FEDERAL 1-30**

API – 05-103-08096



Weeds/Brush/Erosion cuts in blow down pit



Slope not stable –erosion cuts