

HALLIBURTON

iCem[®] Service

EXTRACTION OIL & GAS

Date: Monday, January 22, 2018

Berthoud East Farms 8E-10-11C Production

Job Date: Thursday, January 18, 2018

Sincerely,

Bryce Hinsch

Legal Notice

Warning Disclaimer

Although the information contained in this report is based on sound engineering practices, the copyright owner(s) does (do) not accept any responsibility whatsoever, in negligence or otherwise, for any loss or damage arising from the possession or use of the report whether in terms of correctness or otherwise. The application, therefore, by the user of this report or any part thereof, is solely at the user's own risk.

Limitations of Liability

Except as expressly set forth herein, there are no representations or warranties by Halliburton, express or implied, including implied warranties of merchantability and/or fitness for a particular purpose. In no event will Halliburton or its suppliers be liable for consequential, incidental, special, punitive or exemplary damages (including, without limitation, loss of data, profits, use of hardware, or software). Customer accepts full responsibility for any investment made based on results from the Software. Any interpretations, analyses or modeling of any data, including, but not limited to Customer data, and any recommendation or decisions based upon such interpretations, analyses or modeling are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and assumptions are not infallible, and with respect to which professional may differ. Accordingly, Halliburton cannot and does not warrant the accuracy, correctness or completeness of any such interpretation, recommendation, modeling or other products of the Software Product. As such, any interpretation, recommendation or modeling resulting from the Software for the purpose of any drilling, well treatment, production or financial decision will be at the sole risk of Customer. Under no circumstances will Halliburton or its suppliers be liable for any damages.

Table of Contents

Cementing Job Summary	4
Executive Summary	4
Real-Time Job Summary	7
Job Event Log	7
Attachments.....	10
Berthoud East Farms 8E-10-11C Production Job Chart.....	10

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Berthoud East Farms 8E-10-11C** cement **production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 60 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton [Fort Lupton]

The Road to Excellence Starts with Safety

Sold To #: 369404	Ship To #: 3833879	Quote #:	Sales Order #: 0904576427
Customer: EXTRACTION OIL & GAS		Customer Rep: Shane	
Well Name: BERTHOUD FARMS		Well #: 8E-10-11C	API/UWI #: 05-123-45724-00
Field: WATTENBERG	City (SAP): MEAD	County/Parish: WELD	State: COLORADO
Legal Description: NE SE-7-4N-68W-1548FSL-1002FEL			
Contractor: PATTERSON-UTI ENERGY		Rig/Platform Name/Num: PATTERSON 346	
Job BOM: 7523 7523			
Well Type: HORIZONTAL OIL			
Sales Person: HALAMERICA\HX38199		Srvc Supervisor: Ryan Stevens	

Job

Formation Name			
Formation Depth (MD)	Top		Bottom
Form Type	BHST		
Job depth MD	10677ft	Job Depth TVD	6250
Water Depth		Wk Ht Above Floor	5'
Perforation Depth (MD)	From		To

Well Data

Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing	New	9.625	8.921	36		J-55	0	1545	0	0
Casing	New	5.5	4.778	20	BTC	P-110	0	10677		6250
Open Hole Section			8.5				1545	10690		6250

Tools and Accessories

Type	Size in	Qty	Make	Depth ft	Type	Size in	Qty	Make
Guide Shoe					Top Plug	5.5	1	KLX
Float Shoe	5.5	1	KLX	10,677	Bottom Plug			
Float Collar	5.5	1	KLX	10,673	SSR plug set			
Insert Float					Plug Container	5.5	1	HES
Stage Tool					Centralizers			

Fluid Data

Stage/Plug #: 1										
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
1	11.5 lb/gal Tuned Spacer III	Tuned Spacer III	50	bbl	11.5	3.73	23.4	5		
149.34 lbm/bbl		BARITE, BULK (100003681)								
35 gal/bbl		FRESH WATER								

0.50 gal/bbl		MUSOL A, 330 GAL TOTE - (790828)							
0.50 gal/bbl		DUAL SPACER SURFACTANT B, 5 GAL PAIL (100003665)							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	ElastiCem	ELASTICEM (TM) SYSTEM	1,820	sack	13.2	1.57	7.53	8	13,704
0.45 %		SCR-100 (100003749)							
7.53 Gal		FRESH WATER							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Displacement	Displacement	236.9	bbl	8.34			10	9,949
Cement Left In Pipe	Amount	0 FT			Reason			WET SHOE	
Mix Water:	pH 7	Mix Water Chloride:	200 ppm		Mix Water Temperature:	62 °F			
Cement Temperature:		Plug Displaced by:	8.34 GAL/LB		Disp. Temperature:	134 F			
Plug Bumped?	Yes	Bump Pressure:	2950 psi		Floats Held?	Yes			
Cement Returns:	60 bbl	Returns Density:			Returns Temperature:	°F			
Comment 60 BBLs OF CEMENT BACK TO SURFACE									

2.0 Real-Time Job Summary

2.1 Job Event Log


Type	Seq. No.	Activity	Graph Label	Date	Time	Source	Downhole Density <i>(ppg)</i>	Combined Pump Rate <i>(bbl/min)</i>	Driv-Side Pump Pressure <i>(psi)</i>	Comments
Event	1	Call Out	Call Out	1/18/2018	13:00:00	USER				CREW CALLED OUT FOR JOB. CREW PICKED UP PUMP 11645460, BULK TRUCK, PLUG CNTAINER AND BULK TRUCK FROM FORT LUPTON YARD.
Event	2	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	1/18/2018	14:55:14	USER				CREW DISCUSSED HAZARDS ALONG ROUTE
Event	3	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	1/18/2018	17:45:00	USER				DISCUSS HAZARDS ALONG ROUTE
Event	4	Crew Leave Yard	Crew Leave Yard	1/18/2018	18:00:00	USER				STARTED JOURNEY MANAGEMENT
Event	5	Arrive At Loc	Arrive At Loc	1/18/2018	18:45:00	USER				END JOURNEY MANAGMENT MEET WITH COMPANY MAN AND DISCUSS JOB PROCEDURES
Event	6	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	1/18/2018	19:00:00	USER				CREW DISCUSSED HAZARDS ASSOCIATED WITH RIGGING UP.
Event	7	Rig-Up Equipment	Rig-Up Equipment	1/18/2018	19:10:00	USER				CREW RIGGED UP PUMP AND BULK EQUIPMENT TO PERFORM JOB.
Event	8	Rig-Up Completed	Rig-Up Completed	1/18/2018	19:15:00	USER				EQUIPMENT WAS READY TO PERFORM JOB.
Event	9	Pre-Job Safety Meeting	Pre-Job Safety Meeting	1/18/2018	19:30:00	USER	8.50	8.20	267.00	MEET WITH RIG CREW AND HES PERSONNEL TO DISCUSS JOB PROCEDURES AND JSA.

Event	10	Start Job	Start Job	1/18/2018	19:55:47	COM4	8.42	0.00	-22.00	START RECORDING JOB DATA
Event	11	Test Lines	Test Lines	1/18/2018	20:27:30	COM4	8.46	0.00	5753.00	PRESSURE TEST PUMPS AND LINES TO 5720 PSI. EKO SET @ 500 KICKED OUT @ 1,479 PSI.
Event	12	Pump Spacer 1	Pump Spacer 1	1/18/2018	20:37:05	COM4	8.37	0.00	-7.00	PUMP 50 BBLS OF TUNED SPACER @ 11.5 PPG YIELD 3.73 MIX WATER 23.4. DENSITY VERIFIED BY PRESSURIZED MUD SCALES.
Event	13	Pump Cement	Pump Cement	1/18/2018	20:48:31	COM4	13.23	5.00	249.00	PUMP 1,820 SXS OF ELASTICEM @ 13.2 PPG YIELD 1.57 MIX WATER 7.53. CALCULATED 62 BBLS BACK TO SURFACE.
Event	14	Shutdown	Shutdown	1/18/2018	22:01:27	COM4	13.06	0.10	165.00	SHUT DOWN AND WASH PUMPS AND LINES
Event	15	Drop Top Plug	Drop Top Plug	1/18/2018	22:10:19	COM4				KLX HAND DROPE TOP PLUG. VERIFIED BY COMPANY REP.
Event	16	Pump Displacement	Pump Displacement	1/18/2018	22:10:23	COM4				PUMP CALCULATED DISPLACEMENT OF 236 BBLS
Event	17	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	1/18/2018	22:35:00	USER	8.16	9.60	2878.00	CREW DISCUSSED HAZARDS ASSOATED WITH RIGGING DOWN.
Event	18	Bump Plug	Bump Plug	1/18/2018	22:37:21	COM4	8.15	0.00	2956.00	BUMPED PLUG @ 5 BPM.2,950 PSI. FINAL CIRCULATING PRESSURE @ 2300 PSI. 60 BBLS OF CEMENT BACK TO SURFACE
Event	19	Other	Other	1/18/2018	22:38:49	COM4	8.12	5.00	2249.00	BURST PLUG @ 3,700 PSI AND PUMP 5 BBLS FOR WET SHOE
Event	20	Check Floats	Check Floats	1/18/2018	22:40:38	USER	7.98	0.00	31.00	CHECK FLOATS, FLOATS

										HELD 2 BBLS BACK.
Event	21	End Job	End Job	1/18/2018	22:41:41	COM4	7.97	0.00	-5.00	STOP RECORDING JOB DATA
Event	22	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	1/18/2018	23:00:00	USER	-0.37	0.00	-20.00	CREW DISCUSSED RIG DOWN PROCEDURES AND JSA.
Event	23	Rig-Down Completed	Rig-Down Completed	1/18/2018	23:35:00	USER				EQUIPMENT WAS RIGGED DOWN AND LOCATION WAS CLEAN.
Event	24	Crew Leave Location	Crew Leave Location	1/18/2018	23:59:00	USER				THANKS RYAN STEVENS AND CREW.

3.0 Attachments

3.1 Berthoud East Farms 8E-10-11C Production Job Chart



▼ **HALLIBURTON** | iCem® Service

Created: 2018-01-18 14:39:25, Version: 4.2.393

Edit

Customer: EXTRACTION OIL & GAS-EBUS

Job Date: 1/18/2018 7:25:35 PM

Well: Berthoud East Farms 8E-10-11C

Representative: Ryan Stevens

Sales Order #: 904576427

Pump / Operator: 11645460 / Nick Cummins