

Inspection Photos  
Location Name: Moffat 23-12-89-1  
API: 05-081-06990



**Photo 1. Lease road not maintained in winter.**