

Inspection Photos
Location Name: Moffat 23-12-89-2
API: 05-081-06989



Photo 1. Lease road not maintained in winter.