

Inspection Photos
Location Name: Arapaho State 6-81-36-3
API: 05-057-06507



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Arapaho State 6-81-36-3
API: 05-057-06507



Photo 2. Uncompacted berm.



Photo 3. No battery sign apparent.

Inspection Photos
Location Name: Arapaho State 6-81-36-3
API: 05-057-06507



Photo 4. No wellhead sign apparent.



Photo 5. No wildlife protection apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 689800918