

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2018

Submitted Date:

03/14/2018

Document Number:

675000260**FIELD INSPECTION FORM**

Loc ID 331802 Inspector Name: Duran, Alicia On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                    | Comment                         |
|--------------|-------|--------------------------|---------------------------------|
| ,            |       | cogccinspection@pdce.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 266096      | WELL | SI     | 09/01/2017  | GW         | 123-21324 | WYSCAVER 24-5 | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                 |       |  |
|--------------------|-----------------|-------|--|
| <b>Fencing/:</b>   |                 |       |  |
| Type               | SEPARATOR       |       |  |
| Comment:           | Livestock fence |       |  |
| Corrective Action: |                 | Date: |  |
| Type               | TANK BATTERY    |       |  |
| Comment:           | Livestock fence |       |  |
| Corrective Action: |                 | Date: |  |
| Type               | WELLHEAD        |       |  |
| Comment:           | Panel           |       |  |
| Corrective Action: |                 | Date: |  |

|                           |     |       |                 |
|---------------------------|-----|-------|-----------------|
| <b>Equipment:</b>         |     |       | corrective date |
| Type: Bird Protectors     | # 1 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Plunger Lift        | # 1 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Ancillary equipment | # 2 |       |                 |

|   |     |       |
|---|-----|-------|
| Comment: <a href="#">Automation array</a> |     | Date: |
| Corrective Action:                        |     | Date: |
| Type: Gas Meter Run                       | # 2 |       |
| Comment:                                  |     |       |
| Corrective Action:                        |     | Date: |
| Type: Horizontal Heated Separator         | # 1 |       |
| Comment:                                  |     |       |
| Corrective Action:                        |     | Date: |
| Type: Emission Control Device             | # 1 |       |
| Comment:                                  |     |       |
| Corrective Action:                        |     | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 100 BBLs | PBV FIBERGLASS |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
|---|----------|---------------------|---------------------|-------------|-----------------------|
|   |          |                     |                     |             |                       |
| Comment: <a href="#">Shared berm with crude oil tank.</a> |          |                     |                     |             |                       |
| Corrective Action:  |          |                     |                     | Date:       |                       |
| Contents  | #        | Capacity            | Type                | Tank ID     | SE GPS                |
| CRUDE OIL   | 1        | 400 BBLs            | STEEL AST           |             | 40.337140,-104.461940 |
| Comment:  |          |                     |                     |             |                       |
| Corrective Action:  |          |                     |                     |             | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |



| Inspected Facilities   |        |       |      |             |           |         |    |               |    |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 266096 | Type: | WELL | API Number: | 123-21324 | Status: | SI | Insp. Status: | SI |
| Idle Well  |        |       |      |             |           |         |    |               |    |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |       |      |             |           |         |    |               |    |
| Comment: <input type="text" value="SI"/>   |        |       |      |             |           |         |    |               |    |
| Corrective Action: <input type="text"/> Date: _____  |        |       |      |             |           |         |    |               |    |
| BradenHead   |        |       |      |             |           |         |    |               |    |
| Comment: <input type="text" value="Plumbed to surface"/>   |        |       |      |             |           |         |    |               |    |
| Corrective Action: <input type="text"/> Date: _____  |        |       |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                         | URL   |
|--------------|-------------------------------------|---|
| 675000261    | Photos of tank battery and wellhead | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404763">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404763</a> |