

**Inspection Photos**  
**Location Name: RASMUSSEN 13-29**  
**Facility ID # 300752**



**Photo 1. Wellhead sign**



**Photo 2. Stained soil under muffler**

**Inspection Photos**  
**Location Name: RASMUSSEN 13-29**  
**Facility ID # 300752**



**Photo 3. Flywheel guard unused**



**Photo 4. Stained soil at wellhead**



**Inspection Photos**  
**Location Name: RASMUSSEN 13-29**  
**Facility ID # 300752**



**Photo 5. debris in motor room**



**Photo 6. debris in motor room**

**Inspection Photos**  
**Location Name: RASMUSSEN 13-29**  
**Facility ID # 300752**



**Photo 7. Unused equip. leaking fluid to ground**