

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401573335

Receive Date:

03/15/2018

Report taken by:

BOB CHESSON

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>		Operator No: <u>69175</u>	Phone Numbers
Address: <u>1775 SHERMAN STREET - STE 3000</u>			Phone: <u>(303) 860-5800</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80203</u>	Mobile: <u>()</u>
Contact Person: <u>Karen Olson</u>		Email: <u>Karen.Olson@pdce.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 7693Initial Form 27 Document #: 2232548

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>LOCATION</u>	Facility ID: <u>322943</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>BECKER-63N64W 5NWSE</u>		Latitude: <u>40.252537</u>	Longitude: <u>-104.572604</u>
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NWSE</u>	Sec: <u>5</u>	Twp: <u>3N</u>	Range: <u>64W</u>
Meridian: <u>6</u>		Sensitive Area? <u>Yes</u>	

SITE CONDITIONS

General soil type - USCS Classifications SMMost Sensitive Adjacent Land Use CROP LANDIs domestic water well within 1/4 mile? YesIs surface water within 1/4 mile? YesIs groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

SURFACE WATER ~2,700' W, RESIDENCE ~475' N, WATER WELL ~685' NW, AND DEPTH TO GROUNDWATER ~16' BGS.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☒ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
	GROUNDWATER	REFER TO FIGURE 3 AND TABLE 2	GROUNDWATER SAMPLING
	SOILS	REFER TO FIGURE 2 AND TABLE 1	EXCAVATION, DRILLING, SAMPLING

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A FORM 19 WAS SUBMITTED ON JANUARY 14, 2013 AND THE COGCC ISSUED SPILL #2231641 FOR THIS PROJECT. A TOPOGRAPHIC MAP OF THE SITE IS INCLUDED ON FIGURE 1.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☐ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 0
Number of soil samples exceeding 910-1
Was the areal and vertical extent of soil contamination delineated?
Approximate areal extent (square feet)

NA / ND

 Highest concentration of TPH (mg/kg)
 Highest concentration of SAR
 BTEX > 910-1
 Vertical Extent > 910-1 (in feet)

Groundwater

Number of groundwater samples collected 8
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) 8'
Number of groundwater monitoring wells installed 8
Number of groundwater samples exceeding 910-1 1

-- Highest concentration of Benzene (µg/l) 11
ND Highest concentration of Toluene (µg/l)
ND Highest concentration of Ethylbenzene (µg/l)
ND Highest concentration of Xylene (µg/l)
NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) Volume of liquid waste (barrels)

☒ Is further site investigation required?

PDC FEELS THAT NO FURTHER SITE INVESTIGATION IS REQUIRED AT THIS TIME. THE EXCAVATION EXTENT AND SOIL AND GROUNDWATER SAMPLE LOCATIONS ARE ILLUSTRATED ON FIGURE 2. SOIL ANALYTICAL RESULTS ARE SUMMARIZED IN TABLE 1 AND GROUNDWATER ANALYTICAL RESULTS ARE SUMMARIZED IN TABLE 2 AND ILLUSTRATED ON FIGURE 3.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

THE SOURCE AREA WAS PREVIOUSLY EXCAVATED AND IMPACTED MATERIAL WAS TRANSPORTED AND DISPOSED OF AS DESCRIBED IN THE FORM 19.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Enhanced fluid recovery (EFR) and air sparge (AS) was conducted between the first quarter 2013 and fourth quarter 2016 to address persisting dissolved-phase petroleum hydrocarbon concentrations. Monitored natural attenuation (MNA) was initiated during the first quarter 2017 and continued through the first quarter 2018.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)
☐ _____ Chemical oxidation
Yes _____ Air sparge / Soil vapor extraction
Yes _____ Natural Attenuation
☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

First quarter 2018 groundwater monitoring was conducted on March 7, 2018. Groundwater samples were collected from eight (8) Site monitoring wells (BH01 - BH08). Groundwater samples were submitted to Summit Scientific Laboratories for analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX) by Unites States Environmental Protection Agency (USEPA) Method 8260B. First quarter 2018 analytical results indicated BTEX concentrations were in compliance with COGCC Table 910-1 groundwater standards for the fourth consecutive quarter. Groundwater analytical results are summarized in Table 1 and illustrated on Figure 1.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other No Further Action (NFA) Request

Report Type: ☒ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report
☒ Other No Further Action (NFA) Request

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDATION COMPLETION REPORT

REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? No

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? No

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The excavation area was backfilled and re-graded to match pre-existing conditions. The facility was decommissioned following excavation activities. Monitoring wells will be abandoned and the site will be reclaimed in accordance with COGCC Rule 1004.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☒ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 11/27/2012

Date of commencement of Site Investigation. 11/27/2012

Date of completion of Site Investigation. 11/29/2012

REMEDIAL ACTION DATES

Date of commencement of Remediation. 12/13/2012

Date of completion of Remediation. 03/07/2018

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Based on the analytical results described herein, PDC is requesting a No Further Action (NFA) determination for this location.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Karen Olson

Title: Senior EHS Manager

Submit Date: ` 03/15/2018

Email: Karen.Olson@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: BOB CHESSON

Date: 03/15/2018

Remediation Project Number: 7693

COA Type**Description**

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

401573335	FORM 27-SUPPLEMENTAL-SUBMITTED
401574755	ANALYTICAL RESULTS
401574757	SITE MAP

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

Environmental	The COGCC has reviewed the NFA request for Project/Remediation #7693. Based on the information presented, no further action is necessary at this time. However, should future conditions at the site indicate contaminant concentrations in soils or groundwater exceeding COGCC standards then further investigation and/or remediation activities may be required at the site. For locations with active ongoing oil and gas operations, comply with Rule 1003 interim reclamation requirements and for locations that will no longer have active oil and gas operations, comply with Rule 1004 Final Reclamation requirements.	03/15/2018
---------------	---	------------

Total: 1 comment(s)