

Inspection Photos

API: 05-007-06149

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Date: 2/28/2018



Photo 1. View of the project area from the northeastern corner facing center. Western portion of well pad is being used for staging for what appears to be nearby pipeline work.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is sparse and appears grazed. Appears to largely be comprised of western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of the western portion of the project area from the northwestern corner facing southward.



Photo 5. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 6. View of musk thistles (*Carduus nutans*) within the interim reclamation area. Approximately 150 individuals observed within the project area.