

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401572982

Receive Date:

03/13/2018

Report taken by:

RICK ALLISON

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>SRC ENERGY INC</u>		Operator No: <u>10311</u>	Phone Numbers	
Address: <u>1675 BROADWAY SUITE 2600</u>		Phone: <u>(970) 4755220</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>		Mobile: <u>()</u>
Contact Person: <u>Dave Castro</u>		Email: <u>dcastro@srcenergy.com</u>		

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 11108Initial Form 27 Document #: 401572982

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>LOCATION</u>	Facility ID: <u>424967</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>Ikenouye F 28-65HN TANK</u>		Latitude: <u>40.368300</u>	Longitude: <u>-104.678280</u>
		** correct Lat/Long if needed: Latitude: <u>40.368989</u>	Longitude: <u>-104.678504</u>
QtrQtr: <u>NESE</u>	Sec: <u>29</u>	Twp: <u>5N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications GMMost Sensitive Adjacent Land Use crop landIs domestic water well within 1/4 mile? YesIs surface water within 1/4 mile? YesIs groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	undetermined	groundwater sample
Yes	SOILS	9' deep, horizonatal TBD	soil sampling

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

The partially buried produced water vault has been removed.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Soil grab samples have been collected from the pit bottom, sidewall, and 3 potholes to the east, south, and west of the pit. Those sample locations are shown in the attached Figure 2 and Data Table. Further excavation and soil sampling is proposed closer in than the potholes.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

One groundwater sample has been collected from the bottom of the pit excavation, which is shown on Figure 3 and the Data Table attached. Eagle Environmental proposes to place the 6 monitoring wells shown on the attached Figure 3 to begin groundwater impact extent determination.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 6

Number of soil samples exceeding 910-1 3

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 20

NA / ND

-- Highest concentration of TPH (mg/kg) 800

-- Highest concentration of SAR 4.2

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 9

Groundwater

Number of groundwater samples collected 1

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 9'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 1

-- Highest concentration of Benzene (µg/l) 254

-- Highest concentration of Toluene (µg/l) 1360

-- Highest concentration of Ethylbenzene (µg/l) 70.5

-- Highest concentration of Xylene (µg/l) 1820

NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Partially buried water vault has been removed.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Impacted soil will be further excavated and hauled to North Weld Landfill. Once impacted soil excavation is complete, Eagle Environmental plans to place monitoring wells shown in Figure 3, to begin the groundwater impact extent assessment. Once soil and groundwater impacts extents are determined, Eagle will choose the best remedial approach to the site.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☒ Ex Situ

Yes _____ Excavate and offsite disposal
If Yes: Estimated Volume (Cubic Yards) _____ 36
Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

Yes _____ Bioremediation (or enhanced bioremediation)
Yes _____ Chemical oxidation
☐ _____ Air sparge / Soil vapor extraction
Yes _____ Natural Attenuation
☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

See attached Figure 3 for proposed monitoring well locations to begin the assessment of groundwater impact extent. If more monitoring wells are necessary after the initial 6 are sampled and results show BTEX results above Table 910-1 to any, more MWs will be placed for continued extent determination as needed.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other _____

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report
☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Impacted soils will be excavated and taken to landfill once extents are determined. Excavation will be backfilled with clean dirt and the tank battery liner replaced once all work is done.

Is the described reclamation complete? ☐ No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/13/2018

Date of commencement of Site Investigation. 03/13/2018

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

This Form 27 is for the proposed site impact extent assessment and remediation related to historical spill ID 454240. On 9/1/17, SRC acquired this location from Noble Energy and has since removed the partially buried produced water vaults at the tank battery per document 401543450. After soil sampling, further excavation, and more soil and groundwater sampling, it was determined that a historical spill at this partially buried produced water vault site caused impacts to soil and groundwater. Eagle Environmental will be doing site impact assessment and remediation work at this site for the historical spill on behalf of SRC Energy.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Dave Castro

Title: Sr. Env. Specialist

Submit Date: ` 03/13/2018

Email: dcastro@srcenergy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: RICK ALLISON

Date: 03/16/2018

Remediation Project Number: 11108

COA Type**Description**

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

401572982	FORM 27-INITIAL-SUBMITTED
401573004	MAP
401573005	SOIL SAMPLE LOCATION MAP
401573006	GROUND WATER SAMPLE LOCATION
401573007	ANALYTICAL RESULTS

Total Attach: 5 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)