

Inspection Photos

Location Name: Atlas Resources LLC, DBA Atlas Rockies LLC, Claymon 843-6-41-L8

API: 05-095-06311



1. Lease sign



2. Meter shed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Atlas Resources LLC, DBA Atlas Rockies LLC, Claymon 843-6-41-L8

API: 05-095-06311



3. Wellhead equipment has been removed



4. Gas scrubber



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources