

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/14/2018

Submitted Date:

03/19/2018

Document Number:

680303089**FIELD INSPECTION FORM**
 Loc ID 303070 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 75027Name of Operator: ROSEWOOD RESOURCES INCAddress: 2101 CEDAR SPRINGS RD STE 1500City: DALLAS State: TX Zip: 75201**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Krehmeyer, James	970-848-2228	jkrehmeyer@rosewd.com	Cell # 970-630-3880

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252388	WELL	PR	10/17/1996	GW	125-06262	VINCENT 1-8	PR

General Comment:

Follow-up FIR for Doc# 680001178, CA's have been performed, production reporting current to Jan. 2018

Location

Lease Road:			
Type	Access		
comment:	Located within rotational cropland w/seasonal access		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Steel panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Elec. panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

<u>Venting:</u>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	252388	Type:	WELL	API Number:	125-06262	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	GW								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: Located within rotational cropland w/rotational tillage

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT