

Inspection Photos  
Location Name: McCallum Unit 37  
API: 05-057-06008



**Photo 1. Overview of location taken at entrance facing northwest.**



**Photo 2. Stained soil at wellhead.**