

Inspection Photos  
Location Name: McCallum Unit 50  
API: 05-057-06030



**Photo 1. Overview of location taken at entrance facing north.**



**Photo 2. Drum without secondary containment, fluid in top of tubing.**