

Inspection Photos
Location Name: McCallum 177
API: 05-057-06425



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: McCallum 177
API: 05-057-06425



Photo 2. Stained soil and fluid in tubing.



Photo 3. Close-up of soil staining and fluid.