

Inspection Photos
Location Name: McCallum Unit 84
API: 05-057-06145



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Stained soil at wellhead.