

Inspection Photos
Location Name: McCallum Unit 48
API: 05-057-06028



Photo 1. Overview of location taken at entrance facing west.



Photo 2. Stained soil at wellhead.