

Inspection Photos

API# 071-06435

Operator: Timber Creek

Inspection Number: 680102752

Inspection Date: 3/7/2018





Photo#1:

Overview of Location to Southwest. Arrow indicates plastic Riser pipe that is at GPS position of Well.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06435



Photo#2:
View from Location Center to Northeast

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06435




Photo#3:
View to Southwest down Access Rd leading into Location



Photo#4:
View to Northeast up Access Rd leading out of Location.

March 7, 2018



Photo#6:

2016 Path of Access Rd; view From North to South for better visibility. Location was built at Start pin since 1999 Aerial, shortening Access Rd to be reclaimed.

March 7, 2018