

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2018

Submitted Date:

03/20/2018

Document Number:

679904146**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 321625 _____ Welsh, Brian _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96730Name of Operator: WILLIFORD ENERGY COMPANYAddress: 6060 AMERICAN PLAZA SUITE 760City: TULSA State: OK Zip: 74135**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hubbard, Corky	806-658-9758	whubbard@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207567	WELL	SI	02/01/2017	OW	017-06502	RHOADES 13-31 2	SI

General Comment:[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around electric panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	National 456		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber, day drum and cathodic rectifier		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Ajax gas engine		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 207567	Type: WELL	API Number: 017-06502	Status: SI	Insp. Status: SI
Producing Well				
Comment:	Well is SI at time of inspection. Central tank battery for (Rhoades 5-4, 5-32, 7-32, 6-32, 13-31 #2, 44-31 #5) 4350' ENE @ 38.877860/-102.814420			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT