

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2018

Submitted Date:

03/20/2018

Document Number:

679904148

FIELD INSPECTION FORM

Loc ID 321658 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96730
Name of Operator: WILLIFORD ENERGY COMPANY
Address: 6060 AMERICAN PLAZA SUITE 760
City: TULSA State: OK Zip: 74135

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hubbard, Corky	806-658-9758	whubbard@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207697	WELL	SI	08/01/2016	OW	017-06632	RHOADES 5 7-32	SI

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	<input style="width: 500px;" type="text"/>	
Corrective Action:	<input style="width: 500px;" type="text"/>	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Metal panels around cathodic rectifier		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Prime Mover	# 1			
Comment:	Ajax gas engine			
Corrective Action:		Date:		
Type: Pump Jack	# 1			
Comment:	National 228			
Corrective Action:		Date:		
Type: Ancillary equipment	# 3			
Comment:	Gas scrubber, day drum and cathodic rectifier			
Corrective Action:		Date:		
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 207697 Type: WELL API Number: 017-06632 Status: SI Insp. Status: SI

Producing Well

Comment: Well is SI at time of inspection. Central tank battery for (Rhoades 5-4, 5-32, 7-32, 6-32, 13-31 #2, 44-31 #5) 2000' NW @ 38.877860/-102.814420

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT