

Inspection Photos

API# 071-06397

Operator: Timber Creek

Inspection Number: 680102767

Inspection Date: 3/8/2018





Photo#1:
Overview of Location to North.

March 8, 2018



Photo#2:

View North along unreclaimed Access road leading into Location.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06397



Photo#3:
View of Cut Slope along East side of Location.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06397



Photo#4:
Sign at top of cut slope indicating unutilized top soil stockpile.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06397



Photo#5:
Silt fence at base of fill slope has become debris.
Arrows indicate silt fence position

March 8, 2018

Photo#6:
Refer to Photo#5 for description.





Photo#7:
Close up of Ground conditions on pad surface.

March 8, 2018



Photo#8:
Refer to Photo#7 for description.