

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/12/2018

Submitted Date:

03/14/2018

Document Number:

689701143**FIELD INSPECTION FORM**

Loc ID 335651	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 13 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																															
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																			
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, Caerus Piceance</td> <td></td> <td>COGCC.inspections@caerus oilandgas.com</td> <td>Piceance inspections only</td> </tr> </table>					Contact Name	Phone	Email	Comment	, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only																																																																							
Contact Name	Phone	Email	Comment																																																																																
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only																																																																																
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>282285</td><td>WELL</td><td>PR</td><td>11/15/2012</td><td>GW</td><td>045-11725</td><td>N PARACHUTE WF09C-25I25A596</td><td>PR</td></tr> <tr><td>292025</td><td>WELL</td><td>PR</td><td>11/15/2012</td><td>GW</td><td>045-14573</td><td>N PARACHUTE WF10B-25I25A596</td><td>PR</td></tr> <tr><td>292026</td><td>WELL</td><td>PR</td><td>11/15/2012</td><td>GW</td><td>045-14572</td><td>N PARACHUTE WF10C-25I25A596</td><td>PR</td></tr> <tr><td>292027</td><td>WELL</td><td>PR</td><td>11/15/2012</td><td>GW</td><td>045-14571</td><td>N PARACHUTE WF09A-25I25A596</td><td>PR</td></tr> <tr><td>292028</td><td>WELL</td><td>PR</td><td>08/27/2007</td><td>GW</td><td>045-14570</td><td>N PARACHUTE WF16A-25I25A596</td><td>PR</td></tr> <tr><td>292029</td><td>WELL</td><td>PR</td><td>08/31/2008</td><td>GW</td><td>045-14569</td><td>N PARACHUTE WF09D-25I25A596</td><td>PR</td></tr> <tr><td>292030</td><td>WELL</td><td>PR</td><td>11/15/2012</td><td>GW</td><td>045-14568</td><td>N PARACHUTE WF09B-25I25A596</td><td>PR</td></tr> <tr><td>292031</td><td>WELL</td><td>PR</td><td>11/15/2012</td><td>GW</td><td>045-14567</td><td>N PARACHUTE WF10A-25I25A596</td><td>PR</td></tr> <tr><td>292032</td><td>WELL</td><td>PR</td><td>11/15/2012</td><td>GW</td><td>045-14566</td><td>N PARACHUTE WF10D-25I25A596</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	282285	WELL	PR	11/15/2012	GW	045-11725	N PARACHUTE WF09C-25I25A596	PR	292025	WELL	PR	11/15/2012	GW	045-14573	N PARACHUTE WF10B-25I25A596	PR	292026	WELL	PR	11/15/2012	GW	045-14572	N PARACHUTE WF10C-25I25A596	PR	292027	WELL	PR	11/15/2012	GW	045-14571	N PARACHUTE WF09A-25I25A596	PR	292028	WELL	PR	08/27/2007	GW	045-14570	N PARACHUTE WF16A-25I25A596	PR	292029	WELL	PR	08/31/2008	GW	045-14569	N PARACHUTE WF09D-25I25A596	PR	292030	WELL	PR	11/15/2012	GW	045-14568	N PARACHUTE WF09B-25I25A596	PR	292031	WELL	PR	11/15/2012	GW	045-14567	N PARACHUTE WF10A-25I25A596	PR	292032	WELL	PR	11/15/2012	GW	045-14566	N PARACHUTE WF10D-25I25A596	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																												
282285	WELL	PR	11/15/2012	GW	045-11725	N PARACHUTE WF09C-25I25A596	PR																																																																												
292025	WELL	PR	11/15/2012	GW	045-14573	N PARACHUTE WF10B-25I25A596	PR																																																																												
292026	WELL	PR	11/15/2012	GW	045-14572	N PARACHUTE WF10C-25I25A596	PR																																																																												
292027	WELL	PR	11/15/2012	GW	045-14571	N PARACHUTE WF09A-25I25A596	PR																																																																												
292028	WELL	PR	08/27/2007	GW	045-14570	N PARACHUTE WF16A-25I25A596	PR																																																																												
292029	WELL	PR	08/31/2008	GW	045-14569	N PARACHUTE WF09D-25I25A596	PR																																																																												
292030	WELL	PR	11/15/2012	GW	045-14568	N PARACHUTE WF09B-25I25A596	PR																																																																												
292031	WELL	PR	11/15/2012	GW	045-14567	N PARACHUTE WF10A-25I25A596	PR																																																																												
292032	WELL	PR	11/15/2012	GW	045-14566	N PARACHUTE WF10D-25I25A596	PR																																																																												

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	4" balck poly line in front of gas lift meters.		
Corrective Action:	Comply with Rule 603.f .	Date:	04/13/2018

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 9		
Comment:	Gas lift		
Corrective Action:		Date:	

Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical containers at gas lift meters and separators.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282285	Type:	WELL	API Number:	045-11725	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292025	Type:	WELL	API Number:	045-14573	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292026	Type:	WELL	API Number:	045-14572	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292027	Type:	WELL	API Number:	045-14571	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292028	Type:	WELL	API Number:	045-14570	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292029	Type:	WELL	API Number:	045-14569	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292030	Type:	WELL	API Number:	045-14568	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	292031	Type:	WELL	API Number:	045-14567	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Pass					
		Ditches	Pass			
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			
Ditches	Pass					
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401574763	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4403220">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4403220</a>
689701152	Inspection 689701143 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4403218">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4403218</a>