

Inspection Photos
Location Name: Ray State #13-16
Location ID: 305676



Photo 1: Location, looking NW



Photo 2: Wellhead, looking W



Inspection Photos
Location Name: Ray State #13-16
Location ID: 305676



Photo 3: Stained soil at engine.



Photo 4: Stained soil at engine.

Inspection Photos
Location Name: Ray State #13-16
Location ID: 305676



Photo 5: Stained soil at engine exhaust.