

Inspection Photos  
Location Name: Ranch #1  
Location ID: 317622



Photo 1: Wellhead, looking NW



Photo 2: Stained soil at exhaust



**Inspection Photos**  
**Location Name: Ranch #1**  
**Location ID: 317622**



**Photo 3: Stained soil at engine.**