

Inspection Photos
Location Name: Shable PC GK # 19-99HZ
Location ID: 416924



Photo 1: Location, looking SE



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: Shable PC GK # 19-99HZ
Location ID: 416924



Photo 3: Stained soil at wellhead



Photo 4: Stained soil around H2S scavenger containment

Inspection Photos
Location Name: Shable PC GK # 19-99HZ
Location ID: 416924



Photo 5: Stained soil at gas engine.



Photo 6: Debris in treater house

Inspection Photos
Location Name: Shable PC GK # 19-99HZ
Location ID: 416924



Photo 7: Risers E of treater house