

## Inspection Photos


Location Name: Boxer Water Plant

Location ID: #454039

Inspection Date: March 02, 2018



**Photo #1 – Unlabeled modular steel ASTs with flowline manifold and two-track access road, looking east.**



**Photo #2 – Devegetated area south of modular ASTs overlying former skim pit location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Boxer Water Plant

Location ID: #454039

Inspection Date: March 02, 2018



**Photo #3 – Ancillary equipment located ~100' west of modular ASTs.**



**Photo #4 – Flowline risers located ~130' SW of modular ASTs.**