



Cement Ticket

Rig # Third Party

Customer Name Extraction Oil & Gas Inc	Date Of Service: 2/27/2018
--	--------------------------------------

Location rumer hall 1	Equipment C1003
---------------------------------	---------------------------

Description	Qty	Rate	Amount
P and A Charge(Each)	1.00		
Mileage(Miles)	40.00		
G Cement (Bags)	140.00		
Data Acquisition (Each)	1.00		
Iron Inspection (Each)	1.00		
Sugar(Lbs)	1.00		
Water Delivery (Barrels)	@		
Description	Qty		
Miscellaneous	@		

Description Of Work Start Time 10:00 am Stop Time 03:00 pm

Drove crew to location. Held safety meeting in dog house. spotted in equipment. rigged up cementing unit. Held safety meeting with rig crew. Pressure tested hardline to 2000 psi (held). Pumped 80 sacks (16.38 bbls). Pumped 15.47 bbls of displacement. washed up cementing unit. TOOH with tubing. pumped 60 sacks (12.28 bbls) . pumped 1 bbls displacement. washed up cementing unit. rigged down cementing unit. drove crew back to yard.

Payroll Section						
	Employee	Emp #	Rev Hrs.	Travel Hrs.	Non Rev Hrs.	Total
Supervisor	Jaime, Gustavo	HGR010484	0.00	0.00	0.00	0.00
Operator	Jones, Austin	HGR010492	5.00	0.00	0.00	5.00
Derrick	Bell-Verhey, James M	HGR011008	5.00	0.00	0.00	5.00
FloorHand	Sefcovic, Joseph	HGR010822	5.00	0.00	0.00	5.00
FloorHand	Noss, Sean Joseph	HGR011798	5.00	0.00	0.00	5.00

No Unreported Incidents Per My Signature

Ranger Tool Pusher

Customer/Agent:




Data Tracking Report for Bayou Well Services

Prepared by

Job Summary

Contact		Date	February 27, 2018
Email		Start Time	12:16:42 PM
Phone		End Time	12:50:12 PM
Lease	rumer hall 1	Notes	extraction balance plug 80 sacks (16.38 bbls) 15.47 bbls displacement
County	weld		
State	colorado		
Formation			

rumer hall1





Data Tracking Report for Bayou Well Services

Prepared by

Job Summary

Contact	
Email	
Phone	
Lease	rumer hall 1
County	weld
State	colorado
Formation	

Date	February 27, 2018
Start Time	2:07:14 PM
End Time	2:17:17 PM
Notes	extraction balance plug 60 sacks (12.28 bbls) 1 bbl displacement

rumer hall 1

