

# Inspection Photos

API: 05-067-08524

Operator: BP AMERICA PRODUCTION  
COMPANY

Inspection Date: 3/7/2018



**Photo 1. View of the eastern portion of the project area from the northeastern corner facing southward.**



**Photo 2. View of the southern portion of the interim reclamation area from the southeastern corner facing westward. Revegetation is sparse and largely comprised of intermediate wheatgrass (*Thinopyron intermedium*).**



**Photo 3. View of the western portion of the project area from the southwestern corner facing northwestward.**