

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2018

Submitted Date:

03/21/2018

Document Number:

689300680**FIELD INSPECTION FORM**Loc ID 334610 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone          | Email                                 | Comment                                  |
|------------------|----------------|---------------------------------------|--|
| Elsener, Garrett | (303)-565-4600 | COGCC.inspections@caerusoilandgas.com | <a href="#">all Piceance inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 270995      | WELL | PR     | 01/07/2004  | GW         | 045-09809 | BASS 14-10A (G14W) | PR          |
| 271010      | WELL | PR     | 12/08/2004  | GW         | 045-09822 | BASS 14-6D (G14W)  | PR          |
| 271011      | WELL | PR     | 12/11/2004  | GW         | 045-09823 | BASS 14-14A (G14W) | PR          |
| 271012      | WELL | PR     | 12/24/2004  | GW         | 045-09824 | BASS 14-7B (G14W)  | PR          |
| 271013      | WELL | PR     | 12/20/2004  | GW         | 045-09825 | BASS 14-2D(G14W)   | PR          |
| 271014      | WELL | PR     | 12/15/2004  | GW         | 045-09826 | BASS 14-11B(G14W)  | PR          |

**General Comment:**[Routine General Field Inspection](#)

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Main   |       |  |
| comment:          |        |       |  |
| Corrective Action |        | Date: |  |
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action |        | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: 1-970-625-4209

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | TRASH  |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |
| Type               | WEEDS  |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |
| Type               | DEBRIS |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                               |       |  |
|--------------------|-------------------------------|-------|--|
| <b>Fencing/:</b>   |                               |       |  |
| Type               | SEPARATOR                     |       |  |
| Comment:           | Horse panels around Separator |       |  |
| Corrective Action: |                               | Date: |  |
| Type               | WELLHEAD                      |       |  |
| Comment:           | Horse panels around Wellheads |       |  |
| Corrective Action: |                               | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Vertical Heated Separator   | # 5 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Gas Meter Run               | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Deadman # & Marked          | # 5 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Plunger Lift                | # 6 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| CONDENSATE         | 2 | 500 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |               |  |
|------------------|---------------|--|
| Condition        | Adequate      |  |
| Other (Content)  | Methanol Tank |  |
| Other (Capacity) | 1000 Gallon   |  |
| Other (Type)     |               |  |

**Berms**

|          |          |                     |                     |             |
|----------|----------|---------------------|---------------------|-------------|
| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal    | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment: |          |                     |                     |             |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|  |  |  |
|--|--|--|
|  |  |  |
|--|--|--|

| Inspected Facilities  |   |         |                  |
|-----------------------|---|---------|------------------|
| Facility ID:          | 270995  | Type:   | WELL             |
| API Number:           | 045-09809   | Status: | PR               |
| Insp. Status:         | PR  |         |                  |
| <b>Producing Well</b> |   |         |                  |
| Comment:              | Producing well<br>Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports |         |                  |
| Corrective Action:    | Submit required Form 7(s) to COGCC  |         | Date: 04/21/2018 |
| Facility ID:          | 271010  | Type:   | WELL             |
| API Number:           | 045-09822   | Status: | PR               |
| Insp. Status:         | PR  |         |                  |
| <b>Producing Well</b> |   |         |                  |
| Comment:              | Producing well<br>Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports |         |                  |
| Corrective Action:    | Submit required Form 7(s) to COGCC  |         | Date: 04/21/2018 |
| Facility ID:          | 271011  | Type:   | WELL             |
| API Number:           | 045-09823   | Status: | PR               |
| Insp. Status:         | PR  |         |                  |
| <b>Producing Well</b> |   |         |                  |
| Comment:              | Producing well<br>Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports |         |                  |
| Corrective Action:    | Submit required Form 7(s) to COGCC  |         | Date: 04/21/2018 |
| Facility ID:          | 271012  | Type:   | WELL             |
| API Number:           | 045-09824   | Status: | PR               |
| Insp. Status:         | PR  |         |                  |
| <b>Producing Well</b> |   |         |                  |
| Comment:              | Producing well<br>Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports |         |                  |
| Corrective Action:    | Submit required Form 7(s) to COGCC  |         | Date: 04/21/2018 |
| Facility ID:          | 271013  | Type:   | WELL             |
| API Number:           | 045-09825   | Status: | PR               |
| Insp. Status:         | PR  |         |                  |
| <b>Producing Well</b> |   |         |                  |
| Comment:              | Producing well<br>Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports |         |                  |
| Corrective Action:    | Submit required Form 7(s) to COGCC  |         | Date: 04/21/2018 |
| Facility ID:          | 271014  | Type:   | WELL             |
| API Number:           | 045-09826   | Status: | PR               |
| Insp. Status:         | PR  |         |                  |
| <b>Producing Well</b> |   |         |                  |
| Comment:              | Producing well<br>Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports |         |                  |
| Corrective Action:    | Submit required Form 7(s) to COGCC  |         | Date: 04/21/2018 |



**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <a href="#">Routine General Field Inspection</a> | holtzd | 03/21/2018 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                  | URL   |
|--------------|------------------------------|---|
| 689300681    | DocNum:<br>689300681.3/21/18 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4410912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4410912</a> |