

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2018

Submitted Date:

03/22/2018

Document Number:

689401061**FIELD INSPECTION FORM**
 Loc ID 324474 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		inspection@sginterests.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276683	WELL	PR	08/01/2012	GW	051-06062	MCINTYRE 11-90-14 1	PR

General Comment:

This is a follow up inspection to FIR Doc#689400582 and in response to FIRR Doc#401466268. Any corrective actions not addressed from previous inspections are still applicable.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank signs have been updated.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted Emergency Contact Number 1-866-261-9766

Corrective Action:

Date:

Good Housekeeping:

Type	TRASH		
Comment:	Wood and banding material throughout edge of location. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	276683	Type:	WELL	API Number:	051-06062	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Could not do complete stormwater inspection due to snow cover.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT