

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401583164

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>LINDE INC</u>	Operator No: <u>1375</u>	Phone Numbers
Address: <u>200 SOMERSET CORP BLVD #7000</u>		Phone: <u>(303) 590-9145</u>
City: <u>BRIDGEWATER</u> State: <u>NJ</u> Zip: <u>07083</u>		Mobile: <u>(443) 804-3596</u>
Contact Person: <u>Ned Lundvall</u>	Email: <u>elundvall@eaest.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: _____ Initial Form 27 Document #: 401583164

PURPOSE INFORMATION

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

SITE INFORMATION N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>PIT</u>	Facility ID: <u>112977</u>	API #: _____	County Name: <u>MONTEZUMA</u>
Facility Name: <u>SCHMIDT 2</u>	Latitude: <u>37.364865</u>	Longitude: <u>-108.787596</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SWNW</u>	Sec: <u>24</u>	Twp: <u>36N</u>	Range: <u>18W</u> Meridian: <u>N</u> Sensitive Area? <u>No</u>

SITE CONDITIONS

General soil type - USCS Classifications CL Most Sensitive Adjacent Land Use BLM National Monument

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Ephemeral drainages

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|----------------------------------------------------------|----------------------------------------------------------------|---------------------------------------------------|
| <input checked="" type="checkbox"/> E&P Waste | <input checked="" type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input checked="" type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	~40 ft horizontally and ~20 ft bgs	Geoprobe borings tested with PetroFlag and EC meter

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Remaining water was pumped from the pit. Delineation began of surface soils and then of subsurface soils.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

18 soil samples will be collected from hollow stem auger cuttings. Samples will be composited across two foot intervals. Boreholes are displayed on Figure 1 of the attached work plan. Sample intervals are identified by Borehold ID in Table 1 of the work plan.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Boreholes will be logged to determine the feasibility of bioventing. Bioventing wells will be installed in 4 select boreholes in preparation for a bioventing test.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 201

Number of soil samples exceeding 910-1 19

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 4500

NA / ND

-- Highest concentration of TPH (mg/kg) 1853

-- Highest concentration of SAR 3.7

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 19

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 300'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 0

NA Highest concentration of Benzene (µg/l)

 Highest concentration of Toluene (µg/l)

 Highest concentration of Ethylbenzene (µg/l)

 Highest concentration of Xylene (µg/l)

 Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 1

Volume of liquid waste (barrels) 0

Is further site investigation required?

The proposed sampling effort (see attached work plan) will delineate the vertical extent of impacted soil and provide information for remedial alternatives.

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

This investigation will help guide decisions on remediation methods. The soil around the pit will need to be excavated and the remaining soil is being investigated for bioventing feasibility.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

This investigation will help guide decisions on remediation methods. The soil around the pit will need to be excavated and the remaining soil is being investigated for bioventing feasibility.

Soil Remediation Summary

In Situ

- Bioremediation (or enhanced bioremediation)
- Chemical oxidation
- Air sparge / Soil vapor extraction
- Natural Attenuation
- Other _____

Ex Situ

- Excavate and offsite disposal
- If Yes: Estimated Volume (Cubic Yards) _____
- Name of Licensed Disposal Facility or COGCC Facility ID # _____
- Excavate and onsite remediation
- Land Treatment
- Bioremediation (or enhanced bioremediation)
- Chemical oxidation
- Other _____

Groundwater Remediation Summary

- Bioremediation (or enhanced bioremediation)
- Chemical oxidation
- Air sparge / Soil vapor extraction
- Natural Attenuation
- Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other _____

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

This investigation will help guide decisions on remediation methods. The soil around the pit will need to be excavated and the remaining soil is being investigated for bioventing feasibility. Once remediation is complete, reclamation will be evaluated.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim? Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. 10/30/2017

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 11/27/2017

Date of commencement of Site Investigation. 11/27/2017

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Site investigation report outlines sample results collected during previous investigation. Samples were field screened using a PetroFlag TPH meter, which does not indicated specific hydrocarbons (ie BTEX).

Remedial action will be evaluated as it relates to soil composition. If the soil is determined to be suitable for bioventing, a bioventing pilot test will be conducted.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Ned Lundvall _____

Title: EA Project Manager _____

Submit Date: ` _____

Email: elundvall@eaest.com _____

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: _____

COA Type**Description**

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

401583578	SITE INVESTIGATION PLAN
401583580	SITE MAP

Total Attach: 2 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)