

Inspection Photos
Location Name: DF Ranch #1161-20-22
Location ID: 410133



Photo 1: Location, looking NW



Photo 2: Wellhead, looking E

Inspection Photos
Location Name: DF Ranch #1161-20-22
Location ID: 410133



Photo 3: Damaged NFPA decals



Photo 4: Unused antenna at pump jack

Inspection Photos
Location Name: DF Ranch #1161-20-22
Location ID: 410133



Photo 5: Stained soil in engine house