

Inspection Photos  
Location Name: Marick #7-29  
Location ID: 305689



Photo 1: Location, looking NW



Photo 2: Wellhead, looking W

Inspection Photos  
Location Name: Marick #7-29  
Location ID: 305689



**Photo 3: Tank is open to wildlife entrance, stained soil around tank.**



**Photo 4: Stormwater erosion from center of location, looking NW**