

Inspection Photos

API# 071-06415

Operator: Timber Creek

Inspection Number: 680102762

Inspection Date: 3/8/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Debris that remains on Location.

March 8, 2018




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06415



Photo#2:
View North over Location Center

March 8, 2018



Photo#3:
View South over Location Center



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06415



Photo#4:
View East over Location Center
January 30, 2018



Photo#5:
View West over Location Center



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sun Oil PA Starbuck 1 API#045-05049



Photo#6:
View of Reference Area Vegetation.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06415