


- LEGEND**
-  APPROXIMATE MONITORING WELL LOCATION
 -  DESTROYED MONITORING WELL LOCATION
 -  APPROXIMATE EXCAVATION LIMITS (JUNE 2016)
 -  APPROXIMATE EXCAVATION LIMITS (AUGUST 2017)
 -  APPROXIMATE WELL PAD BOUNDARY
 -  APPROXIMATE EXCAVATION AREAS FOR GROUNDWATER AMENDMENT APPLICATION



SITE MAP
 CUSTY #1
 SW 1/4 SW 1/4 SEC.15 T2S R66W 6PM
 LAT/LONG: 39.87267/-104.76956
 ADAMS COUNTY, COLORADO
 REMEDIATION PROJECT #9711

DATE:	3/21/18
FIG NO.:	1
DRAWN BY:	DC



EAGLE
 ENVIRONMENTAL
 CONSULTING, INC.
 4101 INCA STREET, DENVER, CO 80211
 Ph: 303-433-0479 • F: 303-325-5449

