

Inspection Photos
Location Name: Shable #32-42
Location ID: 410065



Photo 1: Wellhead, looking E



Photo 2: Stained soil at wellhead

Inspection Photos
Location Name: Shable #32-42
Location ID: 410065



Photo 3: Stained soil at exhaust



Photo 4: Stained soil at engine