

Inspection Photos

API# 071-06456

Operator: Timber Creek

Inspection Number: 680102766

Inspection Date: 3/8/2018





Photo#1:

Facing southwest toward the reclaimed access road.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06456



Photo#2:

Location and access road have areas with minimal vegetation growth and some areas of bare ground..

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06456



Photo#3:

Location and access road have areas with minimal vegetation growth and some areas of bare ground. View to Northeast.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06456



Photo#4:

Location and access road have areas with minimal vegetation growth and some areas of bare ground.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06456



Photo#5:
Sign, now Debris will need to be removed.

March 8, 2018



Photo#6:
One piece of Debris will need to be removed. Note bare ground conditions



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06456