

# *Inspection Photos*

*API# 071-06455*

*Operator: Timber Creek*

*Inspection Number: 680102769*

*Inspection Date: 3/8/2018*





Photo#1:  
Overview of Location to Northwest

March 8, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06455





Photo#2:

Site is immediately adjacent to lease road that appears to lead South to access one PR Well.

March 8, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06455





Photo#3:  
Gravel has been left on Site..

March 8, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06455





Photo#4:

There is gully erosion with head cut occurring at one point on the South edge of the Location where stormwater discharges into ravine..

March 8, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06455