

Inspection Photos

Loc# 333373

Operator: Timber Creek

Inspection Number: 680102807

Inspection Date: 3/8/2018





Photo#1:
Overview of Location to Southwest

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#333373



Photo#2:

Vegetation has largely failed on Cut slopes with sediment migration occurring. .

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#333373



Photo#3:

Vegetation is sparse on Fill slopes with erosion occurring on steep Fill slope area towards bottom of slope base. .

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#333373



Photo#4:
Localized areas of staining behind Separator.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#333373