

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2018

Submitted Date:

03/18/2018

Document Number:

688301431**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
317096 _____ Sherman, Susan _____ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95520Name of Operator: WESCO OPERATING INCAddress: 120 S DURBIN STREETCity: CASPER State: WY Zip: 82602**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kirkwood, Tom	(307) 472-4618	tomk@kirkwoodcompanies.com	
Kirkwood, Robert W.	(307) 577-5300	bk@kirkwoodcompanies.com	
Young, Rob		rob.young@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236197	WELL	PR	05/24/1972	OW	121-08687	RUDNIK 33-27	SI

General Comment:[Spill followup inspection](#)

Inspected Facilities									
Facility ID:	236197	Type:	WELL	API Number:	121-08687	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI for tank valve repairs."/>									
Corrective Action: <input type="text"/> Date: _____									

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 6

Comment: Oil was recycled into tank and stained soils were removed. Valves are being replaced with some stained soils to clean up (see attached photos). Fix animal holes in tank berms. Comply with Form 19 I (document #401573183) requirements for sampling and manifests.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 04/20/2018

Reportable: YES

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Comment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401578227	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4406192
688301451	WESCO Rudnick 33-27 Spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4406169