

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: Followup to Pit 111760 closure. Pit was closed under REM 5249 issued to Chevron (former operator) of location now operated by Foundation. REM pre-dated eForm and was closed by F-4 #401568705. A single monitoring well remains on location and has been Table 910-1 compliant for > one year.

Corrective Action: Plug and abandon monitoring well in compliance with CDWR criteria. Well is disconnected and listed as TA since at least 10/2016. This inspection only addressed the REM and does not include other potential necessary corrective actions. Date: 04/30/2018

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300236	Foundation-Chevron 045-06103 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414180