

Inspection Photos  
Well Name: USA 1-22 MR  
Location ID: 312576



Photo 1. Wild Horse area seasonal closure.



Photo 2. Wild Horse area seasonal closure.